

Oil Field Environmental Incident Summary

Incident: 20140125103333 **Date/Time of Notice:** 01/25/2014 10:10

Responsible Party: XTO Energy

Well Operator: XTO ENERGY INC.

Well Name: WOLLAN 6-15

Field Name: BERG

Well File #: 7894

Date Incident: 1/24/2014 **Time Incident:** 15:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 96

Sec: 15

Qtr:

Location Description: Approximately 5 gallons of oil blew off location to the SW covering an area of 25 x50.

Submitted By: Kaylan Dirkx

Received By:

Contact Person: Kaylan Dirkx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	barrels	0.5	barrels	0.5	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 2/4/2014

Risk Evaluation:

None

Areal Extent:

25 x 50

Potential Environmental Impacts:

None

Action Taken or Planned:

Approximately 1/2 bbl of oil was recovered by a vacuum truck. Impacted snow and soil will be removed and hauled to an approved disposal facility.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 2/7/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 2/11/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/11/2014 at 16:28 on location. Spray came out of heater treater, according to report contact. Only a small (1x2 foot) area appears to have visible stain, next to where powerline connects to well pad. No stain visible on field stubble on south side of well pad. According to report contact, landowner has visited field and has no issues.